



9479 W Harness Dr, Boise, ID 83709

**Estimate 13019**

ISSUED: DECEMBER 18, 2024 BY: TYLOR DESILET

EXPIRES:

## Boise Mold Removal

VAT

PO BOX 785  
CALDWELL, ID 83606  
US

ESTIMATE

Task 1.0	Rate	Qty	%	Amount
Blow-in insulation into attic (The attic currently has blow-in insulation, we will be blowing in an addition 6"-8" in the areas that are higher and bringing all areas up to the same height.)	\$1.20	1773	0%	\$2,127.60

Subtotal	\$2,127.60
Total	\$2,127.60

#### INFO & NOTES

---

##### Scope of Work:

Initial Assessment and Setup: On-site evaluation of water damage.

Water Mitigation Services: Water extraction and drying via industrial-grade equipment brought by our team.

Drywall Replacement: Removal and disposal of damaged drywall (9' x 10').

Baseboard and Insulation: Removal and replacement of approximately 10' of baseboard.

Minor Attic Remediation: Assessment and minor remediation of the affected area in the attic.

Roof Repairs: Installation of kickout flashing, including the removal of shingles.

Stucco Pillar Restoration: Open and remove stucco from pillar (2' x 12' on each of 4 sides).

Wall Preparation and Finishing: Taping, mudding, texturing, and painting of the new drywall.

Protective Measures: Floor protection throughout the project duration.

Monitoring and Logging: Dry log monitoring to track moisture levels and ensure proper drying.

Dump Fee: Disposal fee for removed materials.

PPE for Mold Remediation: PPE supplies for 2 people for 1 day.

#### TERMS & CONDITIONS

---

Please take a chance to review your estimate and click accept. For payments over \$1000.00, we require 50% of the payment. The price is subject to change if scope of work increases.

We expect payments upon the completion of the job. There will be a 3% interest charge per month on late invoices.