



PAYMENT PENDING

12287 W Audi St, Boise, ID 83713

From

Boise Mold Removal

Tylor Desilet

PO Box 785

Caldwell, ID 83606

US

Phone: 2084120899

info@boise-moldremoval.com

VAT

INVOICE #

3806

ISSUED ON

October 2, 2023

DUE ON

October 16, 2023

DEPOSIT DUE

\$887.50

BALANCE DUE

\$1,775.00

Attachments



Findings for Work Scope

Task 1.0	Rate	Qty	Amount
Remediate the growth in the attic by the dryer vent and by the guest bathroom where the bathroom fan was disconnected (Clean with a anti-microbial solution that both cleans and prevents future growth. We will also clean up the drier lent around the plywood where the dryer is vented out)	\$1,025	1	\$1,025

Task 2.0	Rate	Qty	Amount
Clean up the crawlspace growth that was caused by the kitchen sink, sprinkler box on the right side of the home, there are several areas.	\$550	1	\$550

Task 3.0	Rate	Qty	Amount
Hook up the guest bathroom fan and the dryer connection in the attic (We will not do any roof work, the roof vent for the dryer line was said to not be proper. We will just connect the 2vent in the attic.)	\$125	1	\$125

Task 4.0	Rate	Qty	Amount
Remove the toilet in the master bathroom to check for any growth underneath it. (There was a moisture reading taken in the master bathroom by the toilet which was elevated. There was signs of moisture that were on the vanity as well. The toilet will be placed in the garage for the plumber to reinstall. All findings under the toilet will be discussed even if everything is okay. If there are issues the client will have evidence through pictures to identify all those findings.)	\$75	1	\$75

TOTAL OWED

SUBTOTAL **\$1,775.00**TOTAL **\$1,775.00****INFO & NOTES**

Please take a chance to review your estimate and click accept. For payments over \$1000.00, we require 50% of the payment. The price is subject to change if scope of work increases.

TERMS & CONDITIONS

We expect payments upon the completion of the job. There will be a 3% interest charge per month on late invoices.