



1254

## Estimate 1254

ISSUED: FEBRUARY 10, 2023 BY: TYLOR DESILET

EXPIRES:

### Boise Mold Removal

VAT

PO BOX 785

CALDWELL, ID 83606

US

#### ESTIMATE

Task 1.0	Rate	Qty	Amount
Remove and replace two pieces of insulation that got wet from the leak where the growth on the subfloor is (Includes removal of insulation, new install of new insulation, most the cost is buying a bag of insulation)	\$225	1	\$225
Task 2.0	Rate	Qty	Amount
Remediate mold-like substance locate in the area where the washer leaked (Treatment with anti-microbial solution that cleans and removes most staining. Includes PPE Personal Protective Equipment for the technician).	\$735	1	\$735

Subtotal	\$960.00
Total	\$960.00

#### INFO & NOTES

Please take a chance to review your estimate and click accept. For payments over \$1000.00, we require 50% of the payment. The price is subject to change if scope of work increases.

#### TERMS & CONDITIONS

We expect payments upon the completion of the job. There will be a 3% interest charge per month on late invoices.