



9351 W Hearthside Dr, Boise, ID 83709

Estimate 9260

ISSUED: JULY 3, 2024 BY: TYLOR DESILET

EXPIRES:

Boise Mold Removal

VAT

PO BOX 785
CALDWELL, ID 83606
US

ESTIMATE

Task 1.0	Rate	Qty	Amount
Repair any drywall issues that are bigger than a quarter. (This may require some areas to be drywall mudded, textured and painted. Other areas may be a simple fix. This price includes materials as well.)	\$1,575	1	\$1,575
Task 2.0	Rate	Qty	Amount
Replace two sets of blinds. Includes new hardware and install.	\$450	1	\$450

Task 3.0	Rate	Qty	Amount
Trim out waterlines upstairs to look more appealing for the house. Includes cutting trim and painting.	\$150	1	\$150
Task 4.0	Rate	Qty	Amount
Fix multiple window seals that are peeling paint and need drywall repair.	\$525	1	\$525
Task 5.0	Rate	Qty	Amount
Fix doors. One handle is bad on the front door. It will need to be keyed to allow the current keys to function accordingly. There is one door that needs the striker plate fixed and the door bondoed by the laundry room. The garage door needs the right handle. It has a handle that doesn't have a striker plate. There is the backdoor where the trim needs to be stripped bondoed and painted. This price includes hardware and labor.	\$1,150	1	\$1,150
Task 6.0	Rate	Qty	Amount
Purchase and install new light cover.	\$100	1	\$100

YET TO BE APPROVED

Subtotal	\$3,950.00
Total	\$3,950.00

INFO & NOTES

Please take a chance to review your estimate and click accept. For payments over \$1000.00, we require 50% of the payment. The price is subject to change if scope of work increases.

TERMS & CONDITIONS

We expect payments upon the completion of the job. There will be a 3% interest charge per month on late invoices.