



2797 Lancaster Dr Boise, ID 83702

### Estimate 1244

ISSUED: FEBRUARY 9, 2023 BY: TYLOR DESILET

EXPIRES:

## Boise Mold Removal

VAT

PO BOX 785

CALDWELL, ID 83606

US

#### ESTIMATE

Task 1.0	Rate	Qty	Amount
Removal all blown-in insulation from attic area directly above the kitchen. (Requires insulation vacuum, removing insulation and taking to the dump. National standards state that if there is growth over 10sqft. then insulation must be removed).	\$1,275.65	1	\$1,275.65
Task 2.0	Rate	Qty	Amount
Remediate mold-like in the attic above the kitchen area. (Areas in attic will be remedied with a sodium-based, anti-microbial solution. There may be HEPA vacuuming of the area required to reassure that no contamination is kicked around).	\$1,425.13	1	\$1,425.13

Subtotal	\$2,700.78
Total	\$2,700.78

#### INFO & NOTES

Please take a chance to review your estimate and click accept. For payments over \$1000.00, we require 50% of the payment. The price is subject to change if scope of work increases.

#### TERMS & CONDITIONS

We expect payments upon the completion of the job. There will be a 3% interest charge per month on late invoices.