



4833 N. Waterfront Way, Boise

### Estimate 972

ISSUED: DECEMBER 28, 2022 BY: TYLOR DESILET

EXPIRES:

## Boise Mold Removal

VAT

PO BOX 785

CALDWELL, ID 83606

US

#### ESTIMATE

Task 1.0	Rate	Qty	Amount
Fix the dryer vent (Dryer vent is not connected properly we will need to take it apart and reconnect with right ducting materials).	\$250	1	\$250

#### YET TO BE APPROVED

Subtotal	\$250.00
Total	\$250.00

## INFO & NOTES

---

Please take a chance to review your estimate and click accept. For payments over \$1000.00, we require 50% of the payment.

## TERMS & CONDITIONS

---

We expect payments upon the completion of the job. There will be a 3% interest charge per month on late invoices.