

7736 W Long Drive, Boise

Invoice 2200

ISSUED: MAY 10, 2023 BY: TYLOR DESILET

DUE:

Boise Mold Removal

May 24, 2023

PO BOX 785 VAT

CALDWELL, ID 83606

US

PAID

| Task 1.0 | Rate | Qty | Amount |
|--|---------|-----|---------|
| Remove and replace the blow-in insulation that is over | \$3,600 | 1 | \$3,600 |
| the master bedroom upstairs (The growth exceeds the | | | |
| 10 sqft. minimal, which the IICRC states the insulation is | | | |
| to be removed. This will require us to remove the blow-in | | | |
| insulation with an insulation vacuum and blow new | | | |
| insulation in with a machine. Includes dump fees as | | | |
| well). | | | |
| | | | |

| Task 2.0 | Rate | Qty | Amount |
|---|---------|-----|---------|
| Remediation in both attic accesses with an anti- | \$2,125 | 1 | \$2,125 |
| microbial solution (There is a 3yr. transferable warranty | | | |
| with the home upon completion). | | | |

TOTAL PAID

| Subtotal | \$5,725.00 |
|----------|------------|
| Total | \$5,725.00 |
| Payments | \$5,725.00 |
| Balance | \$0.00 |

INFO & NOTES

Please take a chance to review your estimate and click accept. For payments over \$1000.00, we require 50% of the payment. The price is subject to change if scope of work increases.

TERMS & CONDITIONS

We expect payments upon the completion of the job. There will be a 3% interest charge per month on late invoices.

WordPress Appliance - Powered by TurnKey Linux