



841 Sage Creek Rd Nampa

Estimate 2374

ISSUED: MAY 22, 2023 BY: TYLOR DESILET

EXPIRES:

Boise Mold Removal

VAT

PO BOX 785
CALDWELL, ID 83606
US

ESTIMATE

Task 1.0	Rate	Qty	Amount
Remove the insulation from the affected spot under the bathroom toilet.	\$275	1	\$275
Task 2.0	Rate	Qty	Amount
Clean and treat affected joists under bathroom toilet.	\$600	1	\$600
Task 3.0	Rate	Qty	Amount
Install new insulation in the crawl where insulation was removed by us.	\$390	1	\$390

Subtotal	\$1,265.00
Total	\$1,265.00

INFO & NOTES

Please take a chance to review your estimate and click accept. For payments over \$1000.00, we require 50% of the payment. The price is subject to change if scope of work increases.

TERMS & CONDITIONS

We expect payments upon the completion of the job. There will be a 3% interest charge per month on late invoices.